


Plan otworów w maszynowni podz. 1:50



1000 100 200 300 400 500 600 700 800 900 1000
1000 100 200 300 400 500 600 700 800 900 1000
1000 100 200 300 400 500 600 700 800 900 1000
1000 100 200 300 400 500 600 700 800 900 1000